Operations - a division of Necsa SOC Ltd

Pretoria 0001 | 15 +2712 305 3950

PO Box 582 | 15 +2712 305 3937 | 15 cheryl.akortia@necsa.co.za

South Africa | 50 +2783 635 1538

www.necsa.co.za



OPERATIONS

Manager: NTW Projects National Nuclear Regulator P.O.Box 7106 CENTURION 0046

Our Reference: NIL11A0110 Enquiries: TC Akortia Doc. No. NLM-LET-13/253 Date: 29 November 2013

ATTENTION: Mr. T Pather,

Dear Sir,

NUCLEAR OCCURRENCE NIL11-OCC-0009: RAIN WATER ENTERED PELSTORE DURING A SEVERE STORM WHICH CAUSED MAJOR DAMAGE TO THE ROOF OF AREA-14

INFORMATION CATEGORY	INFORMATION
Date of occurrence	2013/11/28
Date of initial notification	2013/11/29
Facility area	Pelstore Cen /12/ C
Reporting reference	NIL11A0110 SWO-NCR-2013/0032 SHEQ event no: 201311018
Responsible Manager	TC Akortia
Problem Title	Rain water entered Pelstore during a severe storm which caused major damage to the roof of Area-14
Category of occurrence according to SHEQ-INS-4140	Category 2 B10 - Transgression of statutory requirements.
INES Rating according to SHEQ-INS-4145 Appendix B	(<1) Not ratable
Immediate consequences	Due to the damaged roof, the water entered the store.
Sequence of the event in as much detail as possible at the time	 28 November 2013: Severe storm started around 17h00 29 November 2013: Assessment around the facility was conducted 29 November 2013: Event (201311018) registered on the EMP 29 November 2013: Written notification of event sent to NNR
Corrective measures	None
Other relevant information	Pelstore has a secondary steel roof /ceiling underneath the damaged one (this secondary roof is still intact). The rain water which landed on the secondary roof spilled over at the

Directors Ambassador MJ Seekoe (Chairperson), Ms NJ Mxakato-Diseko (Deputy Chairperson), Mr J Kellerman, Mr M Khoathane, Prof T Majozi, Mr ZS Mbambo, Ms MM Mokuena, Ms E Monale (alternate director to Mr ZS Mbambo), Adv N Shaik-Peremanov, Mr PZR Zwane, Mr GP Tshelane (CEO)







edges of this roof at the Pelstore walls. Thus rain water only ran down the walls into the storage area.

Due to the severity of the damage (at least one third of the roof is damaged), it is foreseen that the repair will take a long time.

Until the roof is repaired, further rain water will enter again the store. Preliminary investigation is currently done to establish secondary means to limit the spread of possible further rain water inside the store. These measures shall be implemented as soon as possible.

Detail investigation will be carried out within seven days.

Please address all correspondence in this regard to the Manager: Solid Waste Operations

Yours faithfully

TC Akortia

Manager: Solid Waste Operations

Cc.:

PDO Records (LM Kaibe) S&LD Record (P Nieman) S&LD Records (M Le Roux)

NLM Records (CJE De Jager)

L Hordijk MP Grobler

AR Davids BS Ntshabele IE Stevn AB Myoli

AC Carolissen

TC Akortia

ES Tshabalala

NJ v/d Merwe GR Liebenberg S Mosoeunyane' M Oosthuizen V Ditsi

H Swart