

Operations – a division of Necsa SOC Ltd

PO Box 582 | (012)3056033
Pretoria 0001 | (012)3056891082
South Africa | 0828065332

William.ntho@necsa.co.za
www.necsa.co.za



Manager: NTW Projects
National Nuclear Regulator
P O Box 7106
Centurion
0046

Our Reference: NIL06A0060
Document No: NLM-LET-13/267
Enquiries: W Ntho
Date: 12 December 2013

ATTENTION: Mr T Pather

Dear Sir

**NUCLEAR INSTALLATION LICENCE NIL06: INITIAL NOTIFICATION OF A CATEGORY 2, B9
EVENT – OCCURRENCE NUMBER NIL06-OCC-0011 MISPLACED INSTRUMENT CALIBRATION
SOURCE DU-10**

INITIAL NOTIFICATION	
ITEM	REMARK
Date and Time of the occurrence	2013/11/27
SHEQ event notification, Date, time and number	201311017
Date and time of initial notification	2013/12/12 at 09:00
Facility and Area	Decontamination Facility - Building A-8
Responsible Manager	W Ntho
Description of event	Instrument calibration source DU-10 was misplaced at the A8 facility and was found again. The event was initially categorized as a Cat1, B9 event but was however upgraded during the investigation by the RPS to a Cat2, B9.
Occurrence Category (SHEQ-INS-4140):	Category 2
Occurrence Attribute/s	B9
INES rating:	0

Please address all correspondence in this regard to the Manager: Decontamination Services.

W Ntho
Acting Manager: Decontamination Services

AC Carolissen
Senior Manager: NLM

cc: NLM Records RW Damon
S&LD Records GR Liebenberg
JS Oosthuysen DS Records
MP Grobler N vd Merwe

Directors Ambassador MJ Seekoe (Chairperson), Ms NJ Mxakato-Diseko (Deputy Chairperson), Mr J Kellerman, Mr M Khoathane, Prof T Majazi, Mr ZS Mbambo, Ms MM Mokuena, Ms E Monale (alternate director to Mr ZS Mbambo), Adv N Shaik-Peremanov, Mr PZR Zwane, Mr GP Tshelane (CEO)

Company Secretary Mr ACMabunda

REG. 2000/003735/06

